



FTA614



• Technical Parameters

Specifications	Technical data
Rated torque	5/10/20/50/100N.M
Speed range	≤8000rpm/min
Torque signal	RS485/ ± 10V/ ± 5V/0-10V/0-5V/5-15KHz
Speed signal	RS485/60Pulse Signal
Precision	± 0.2%F.S
Overload capacity	150%
Operating Temperature	-20~80°C
Temp.effect on zero	0.15%F.S./10°C
Temp.effect on output	0.15%F.S./10°C
Power supply	24VDC ± 15%
Material Quality	Shell: Aluminum; Axis: 17-4PH
Cable size	φ 6 × 3000mm

• Mounting Dimensions in mm

